

# Federal Energy Act Report

October 1, 2009 thru September 30, 2010

(Public Record Posted Date: October 5, 2010)

## General Information:

Total Number of Active UST Facilities: **7,946**  
 Total Number of Active/Inactive USTs: **21,595**

## Summary Information For On-Site Inspections:

Number of UST Facilities Inspected: **3,347**  
 Percent of UST Facilities in SOC Compliance: **55**

## Summary Information For Releases:

Number of Confirmed UST Releases: **355**

## Sources and Causes of Environmental Releases from Underground Storage Tanks in Illinois

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	288	81.1	0	0	1	0.3	65	18.3	46	12.9	1	0.3	21	5.9	154	43.4
Piping	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Dispenser	1	0.3	1	0.3	0	0	0	0	0	0	0	0	0	0	0	0
Submersible (STP)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Delivery Problem	77	21.7	32	9	45	12.7	0	0	0	0	0	0	0	0	0	0
Other	1	0.3	0	0	0	0	0	0	0	0	0	0	0	0	1	0.3
<b>Totals</b>	<b>367</b>	<b>103.4</b>	<b>33</b>	<b>9.3</b>	<b>46</b>	<b>13</b>	<b>65</b>	<b>18.3</b>	<b>46</b>	<b>12.9</b>	<b>1</b>	<b>0.3</b>	<b>21</b>	<b>5.9</b>	<b>155</b>	<b>43.7</b>

(source of data: Illinois Environmental Protection Agency)

**Note:** Since a release could be from more than one source and/or could have more than one cause, the percentages within source and cause do not add up 100. For the same reason, the release numbers for each category within source and cause do not add up to total number of confirmed releases. Spill and overfill at the tank are counted as delivery problem and not tank.

To view site specific information at the Office of the State Fire Marshal, please visit: <http://webapps.sfm.illinois.gov/ustsearch/>

To view the LUST Incident Tracking Database, please visit: <http://epadata.epa.state.il.us/land/ust/Search.asp>